



**ICS-CERT**

**INDUSTRIAL CONTROL SYSTEMS CYBER EMERGENCY RESPONSE TEAM**

---

# ICS-CERT ADVISORY

ICSA-10-322-02— AUTOMATED SOLUTIONS OPC SERVER VULNERABILITY

November 18, 2010

## OVERVIEW

The ICS-CERT has received a report from independent security researcher Jeremy Brown that reveals a vulnerability in the Automated Solutions Modbus/TCP Master OPC server. Automated Solutions has confirmed that their most recent patch mitigates the vulnerability for Version 3.0.0. ICS-CERT has verified that the software update resolves the vulnerability identified by the researcher.

## AFFECTED PRODUCTS

This vulnerability affects the Automated Solutions Modbus/TCP Master OPC Server product (Version 3.0.0) and all previous versions.

## IMPACT

Automated Solutions' customers include a large cross section of ICS vendors, including Supervisory Control and Data Acquisition (SCADA) vendors who also supply OPC server products to end users and integrators.

While an exploit is unlikely to allow arbitrary code execution, the impact to individual organizations depends on many factors that are unique to each organization. ICS-CERT recommends that organizations evaluate the impact of this vulnerability based on their environment, architecture, and product implementation.

## BACKGROUND

Automated Solutions supplies Modbus/TCP OPC Data Access OPC servers in an original equipment manufacturer (OEM) version and a stand-alone version. This advisory currently applies only to the stand-alone version.

## VULNERABILITY CHARACTERIZATION

Vulnerability details will be released in a future update to this advisory.

## MITIGATION

ICS-CERT recommends that users of the Automated Solutions Modbus/TCP Master OPC Server (stand-alone) take the following mitigation steps:

- Upgrade to the latest version and install the latest patch.



## ICS-CERT

### INDUSTRIAL CONTROL SYSTEMS CYBER EMERGENCY RESPONSE TEAM

Automated Solutions has developed a patch for the OPC Server (Version 3.0.0); ICS-CERT has verified that the software update resolves the vulnerability identified by the researcher. The patch is available at <http://automatedsolutions.com/demos/demofrom.asp?code=17>.

- Minimize network exposure for all control system devices. Critical devices should not directly face the Internet. Control system networks and remote devices should be located behind firewalls, and be isolated from the business network. If remote access is required, secure methods such as Virtual Private Networks (VPNs) should be utilized.

Owners and operators should exercise caution and consult their control systems vendor prior to making any changes. Proper impact analysis and testing should always be conducted prior to making any changes to control systems.

Organizations should follow their established internal procedures if any suspected malicious activity is observed and report their findings to ICS-CERT for tracking and correlation against other incidents. ICS-CERT reminds organizations that proper impact analysis and risk assessment should be performed prior to taking defensive measures.

The Control System Security Program also provides a recommended practices section for control systems on the US-CERT web site. Several recommended practices are available for reading or download, including *Improving Industrial Control Systems Cybersecurity with Defense-in-Depth Strategies*.<sup>1</sup>

## ICS-CERT CONTACT

For any questions related to this report, please contact ICS-CERT at:

E-mail: [ics-cert@dhs.gov](mailto:ics-cert@dhs.gov)

Toll free: 1-877-776-7585

For Control System Security Program Information and Incident Reporting: [www.ics-cert.org](http://www.ics-cert.org).

## DOCUMENT FAQ

**What is an ICS-CERT Advisory?** An ICS-CERT Advisory is intended to provide awareness or solicit feedback from critical infrastructure owners and operators concerning ongoing cyber events or activity with the potential to impact critical infrastructure computing networks.

1. Control System Security Program (CSSP) Recommended Practices, [http://www.us-cert.gov/control\\_systems/practices/Recommended\\_Practices.html](http://www.us-cert.gov/control_systems/practices/Recommended_Practices.html)